

Watershed Protection District

San Antonio Creek Spreading Grounds Rehabilitation Project Ojai Valley, CA

Ribbon Cutting Event Slideshow



Project Funding

- Proposition 50 Integrated Regional Water Management Grant (2007)
 - \$1,315,000 grant award from State Water Resources Control Board
 - Minimum local match of \$108,746 from Project Stakeholders
- Proposition 84 Round 1 IRWM Implementation Grant, Amendment 1 (2013)
 - \$500,000 grant award from California Department of Water Resources



Project Partners

- Ojai Basin Groundwater Management Agency
- Ojai Water Conservation District
- Golden State Water Company
- Casitas Municipal Water District
- Ventura County Watershed Protection District



Acknowledgements

WPD & County Staff


- Sue Hughes
- Peter Sheydayi
- Gerard Kapuscik
- Elizabeth Martinez
- Pam Lindsey
- Martha Symes
- Matt Hespenheide
- Bill Carey
- Rick Viergutz
- Barbara Council
- Keith Filegar
- Dave Jackson
- Kathy Jones
- Dan Romero

Design

- Jordan Kear, Kear GW
- Daniel B. Stephens
- Penfield & Smith
- Geotechnical
 - **BTC Labs**
- Environmental
 - **Analytical Environmental**
 - BioResource Consultants
 - Padre Associates, Inc.
 - Stillwater Sciences
- Construction Management
 - Penfield & Smith
 - Don Morin, BTC Labs



Regional Location Map





Project Site Vicinity Map





Historical Aerial Photographs





Early evidence of a series of ponds on both the north and south sides of San Antonio Creek. VCWPD did not purchase the parcel until 1986, but the property lines are shown as a frame of reference.

SAN ANTONIO CREEK AREA OF SPREADING GROUNDS/DEBRIS BASIN DATE: APRIL, 1968



1989




When the debris basin was constructed in 1986, the excavated soil was placed on the spreading grounds. In this 1989 photo, the ponds are no longer visible.


SAN ANTONIO CREEK AREA OF SPREADING GROUNDS/DEBRIS BASIN DATE: JUNE, 1989






Historical Aerial Photographs







Project Site Plan





Pre-Project Site Conditions

Existing Spreading Grounds Pond



View East

San Antonio Ck near Intake Location



View Downstream (west)



CEQA Compliance

- Draft Initial Study and Mitigated Negative Declaration (MND) prepared January 2011
- Impact Areas identified in the IS/MND
 - Air Quality
 - Cultural Resources
 - Transportation & Circulation
 - Water Resources
- All impacts less-than-significant with mitigation
- Last minute request by City of Ventura before Board of Supervisor's hearing on April 26, 2011
 - New mitigation measure requiring District to enter into an Operations Agreement to protect senior water rights



Challenge #1: Project Permitting

- Streambed Alteration Agreement from CDFW
- Section 404 Permit from USACE
- Section 401 Water Quality Certification from Los Angeles RWQCB
- Water Right Permit from the State Water Resources Control Board



Endangered Steelhead Trout

- Project site u/s of steelhead critical habitat
- 2007 and 2010 steelhead habitat studies find "limited and marginal steelhead migratory, spawning, and rearing habitat in San Antonio, Senior, and Gridley Creeks"
- However, NMFS cites survey: 3 dead steelhead

Attachment 2 Oncorhynchus mykiss mortalities in upper San Antonio Creek, July 2011. Andrew L. Bonsignori and Scott D. Lewis On 26 July 2011, at 1050 h, three dead O. mykiss were found downstream of the confluence of Senior Canyon and Gridley Canyon creeks at coordinates: N 34.46599, W 119.20564. The O. mykiss were in a small pool where the water was going subsurface (i.e., there was no water downstream from that point). There was an impediment upstream of the pool with a series of small steps that totaled about 2 m in height, the individual steps were up to about 0.8 m (Figure 1). The water depth was estimated to have been no more than about 8 cm. O. mykiss # 1 was 22 cm FL and 23 cm TL (Figure 2). O. mykiss # 2 was 22.3 cm FL and 23 cm TL (Figure 3). O. mykiss # 3 was 29.1 cm FL and 30.6 cm TL (Figure 4). Based on appearance and oder, they were not likely dead for very long. There were no visible marks to their bodies from predators or scavengers. The fish were left in the pool and not removed from the site. The pool was revisited at 1822 h to measure water temperature and dissolved oxygen and it was found to be dry. Measurements were taken in the next small pool upstream. This pool was approximately 22 cm deep. The water temperature at 1822 h was 26.5 °C and the dissolved oxygen was 5.89 mg/L and about 74% of saturation. On the following morning of 27 July at 0825 h, the same pool had a temperature of 17,1 °C and the dissolved oxygen was 8.46 mg/L and 89% of saturation

3 dead steelhead found July 2011



Water Right Application – Resolution of Protests

- Protests received February 2011 from CDFW, NMFS, CalTrout, and City of Ventura
- Main issues bypass flows for steelhead, low flow crossing, maintain senior water rights
- Resolution efforts written correspondence, meetings & teleconferences, lots of additional data, requirement for Operations Agreement, developed Adaptive Management Plan, agreed to 1-foot depth minimum bypass flow, and additional stream flow monitoring



Cobble Low Flow Crossing

Arizona Crossing Not Allowed



Cobble Crossing Constructed






Operating Parameters

(Revisions due to Permit Conditions Shown in "Red")

- Ojai Valley Groundwater Basin recharge estimates:
 - average 308 126 ac-ft over 12 6 days
 - 914 acre-feet annual maximum
- Diversion begins when min. flow criteria met:
 - 0.6 1-foot depth at Grand Avenue (new gage)
 - (Approx. 5 cfs 21 cfs at Grand Ave)
 - 40 50 cfs at Casitas Vista gage on Ventura R.
- Diversion begins when approx. >10.6 cfs >30 cfs at intake



Comparison of San Antonio Creek Flows and Proposed Diversion Flows





Intake Structure Fish Screen & Automatic Cleaning Device



Fish screen panels constructed of V-wire profile bar with <0.0689-inch width openings

Screen cleaning device: rotating bars spray water from inside





Challenge #2: Inadequate Construction Funding in 2012

WP12-022

Bids Opened 7/3/12

oro Enterprises rtW Salas Inc A Rusmussen, In-O Box 6785 0769 Woodside Ave. Ste 201 8548 Jynaston Av merd EA9303 ntee .CA 90071 MODIA: CA 91355 47,150.00 47,150.00 23/000.00 23 000 0 Diversion, Control & Removal of Water 13,400.00 Shoring and Womer Safety 8,500.00 6.500 00 6,000,00 8.000 00 3,000,00 3,000 00 17,550.00 7 650:00 Cleaning and Grubbing 24,100,00 24,100.00 80,000.00 80,000.00 Scartving Ponce 5,750.00 5,750.00 0,800,00 5,800.00 3,000.00 3 550 00 Fig and Backta 5,370.00 5,370.00 \$1,900.00 31,000.00 16,000.00 15,000.00 Too Backfill 9,700.00 2.700.00 3503.00 2.500.00 11,000.00 11,000 00 Jacking Fit or Flatform 23 800 00 23 800 00 15,000,00 15,000,00 39,000.00 29 000 00 5 1,151 00 402,850.00 1,170.00 409,500.00 1,200 00 420,000.00 Jacking Steel Casing Vi Ton Class Concrated Work Ripean. % Ton Class Rock Riprap and Ritter Reviets 3,392.00 135.00 3 840 00 Pra-Cast RC Oversion Structure 48 700 00 48 700 00 44,300 00 44.300.00 26 000.00 25,000 00 Fish Screen 8.500 O 6.500.00 8 483 00 5480 00 1,900.00 1.900.00 Reinforced Concrete Structures 750.00 16 720 00 885:00 19:470:00 770.00 15,940.00 Flow Meter, Flume, and Appurtenances 29,410.00 24" Knife Gate Valves and Vaults 87,440 00 82,300.00 12" Know Gate Valves and Vaulty 11,160,00 44 540 00 9,000,00 36,000,00 7,700.00 30,800.00 24 Inch HDPE Recharge Pipeline 143.30 57.320.00 75.00 30.400.00 48 000 00 59.00 12-Inch HDPE Papeline 15.505 DO £,260 (b) 110 00 15,400.00 Filpeline Cleancut Riser & Timust Block 8,330,00 5 200 00 88,630,00 85,200.00 94,000.00 Scunding and Evacuation Tube 11270.00 53.00 10,600.00 12.830.00 Recharge Well Casing 354.40 52 020 00 35300 61 750 (O) S 350,00 88 250 no a Equitor Fine 121.13 24 226 00 118.00 23.600.00 5 130.00 35 000 00 3 Grave Pack 6,482.00 6,370.00 3 5,250 00 5 0.500.00 0.360.00 Contonite Seal 1,292 00 5,168.00 1,280.00 5 120 00 3 1,730.00 B,920.00 S Cement Grouting of Anniaus 24 962 50 21 875 00 3 140.00 24 500 00 3 Remarge Well Surface Completion 8,430.00 12.660.00 5.860.00 11,720 00 8 7,000.00 14,000.00 Limited Development, Per Flush 3,820,00 3056000 8,739.00 29.840 00 S 4.200.00 33,600 00 3 IE Water by 5' High Chair Link Gates 4,140.00 600,00 1,800,00 5 V (500-00 5,400.00 CMR Arrass Dong 15.20 30 686 66 5.00 21,600,00 \$ 15 dog no 455.00 820 DD Prog Botardy 905.00 2,885.00 1365 00 2.550.60 Link Flow Canssing 20, 800 00 20,800 00 8:300:00 £ 300 m 17,000,00 17.000.00 6,685 (0) 8,455.00 6,455 (0) 5,200,00 5,200 (0) Hydroseeding 1,00 1.00 TOTAL Schedule / Subcontracted Items (Including all of item 11) 42% 45% 655 982 DO 509 935 00 555,800.00 253,032.00 Subcontracted Items (Excluding a) of item (1) 12.000.00 Sounding and Evacuation Tube 65,000 Recharge Well Casing 351.00 61,425.00 350.00 61.250.00 3 390.00 68 250 on 15 Eductor Pice 116.00 23 600 00 118 00 23.600 00 5 28 000 00 3 Gravel Pack 453.00 6.342.00 455.00 6.370.00 5 590.00 8,260 00 3 3,195.00 6,390.00 3,195,00 6,350.00 4:200:00 E400.00 5 Eductor Tee. 140.00 Cement Growting of Annuals 122 50 2143150 21.875 00 3 24.500.00 Fortharde Well Stafface Completion 5.886.00 13.720.00 9 5.863.00 11.720.00 5 9,000,00 14 000 00 5 Limited Development, Per Fladi 5730.00 29,640.00 3 \$785.00 29.840 00 S 4.200.00 33,000.00 S 1 (89 (72.50) 1,089,759.00 Subcontracted Items linduding all of Item ITI 15% 7 009 716:00 Subtratracted tems (Excluding at of Iram 11)

Low Bid \$1,719,414.50

Remaining Available Prop 50 funds = \$1M in 2012



Challenge #3: Site Access








Contract Change Order #1

CCO #1 \$7,000 Realign Access







Remote Site Location

Before



After





Rehabilitation of Four Ponds



March 15, 2010

September 11, 2013





Access Road to Intake Area







May 23, 2014

September 10, 2014

Ventura County Watershed Protection District



Accidental Rupture & Repair of Private Water Line





Drilling Four Recharge Wells



April 2014



Trenching 24" HDPE Pipe from Pond 4 to Recharge Wells





Heat Fusion Welding HDPE Pipe





Preparing to Jack & Bore 36" Steel Casing and 24" HDPE Pipe



November 2013






Jack & Bore (Cont.)



Ventura County Watershed Protection District



Jack & Bore (Cont.)



Ventura County Watershed Protection District



Welding Casing Segments



December 3, 2013

12/03/2013



SUCCESS! 24" Pipe Daylights in Shoring on Opposite Side





Intake Site Preparation



October 1, 2013

January 2, 2014





50-Ton Crane to Lift Pre-Cast Concrete Intake Structure



Ventura County Watershed Protection District



Intake Structure Placement



January 23, 2014





Placement of Actuator Valve Box



February 12, 2014






Storm Event – March 1, 2014 Approx. 80 cfs



Ventura County Watershed Protection District



Temporary Stream Gage Near Intake Structure



Ventura County Watershed Protection District



New Permanent Gage Installed at Grand Avenue Bridge Weir









New Edison Power Pole & Meter



Ventura County Watershed Protection District



Relocate House Finch Fledglings



Source: CalPhotos

House Finch

Nest Found in Crane Pulley





New Radio Antenna & Power Pole



June 6, 2014





Delivery of Actuator Valve & Fish Screen Cleaning Mechanism





June 6, 2014



Next Steps

- Electrical equipment testing (flow meter, fish screen cleaner, valve & actuator)
- Final walk-through & release of contractor
- Ribbon Cutting Ceremony (September)
- Operations Agreement w/City of Ventura
- Continue stream flow monitoring and reporting to NMFS and CDFW
- Mitigation implementation and monitoring



On Site and Off Site Mitigation



On Site Hydroseed March 20, 2014

Off Site Giant Reed Removal November 14, 2013






Monitoring & Reporting

- Annual Flow Monitoring Report
- Annual Steelhead Surveys
- Groundwater Monitoring Plan & Reporting
- Mitigation Monitoring & Reporting
- Maintain Records of Diversion & Use and report annually via eWRIMS



Thank you



Ventura County Watershed Protection District