



01T_ODD2_DCH

Duck Pond Agricultural Drains / Mugu Drain / Oxnard Drain No. 2. The monitoring site is located on an agricultural drain just south of Hueneme Road near the Duck Ponds. Flow from this drain eventually discharges into the western arm of Mugu Lagoon (Calleguas Creek Reach 1).




01T_ODD3_ARN

Rio de Santa Clara / Oxnard Drain No. 3. The monitoring site is located on an agricultural drain just upstream from the Arnold Road Bridge. Flow from this drain eventually discharges into the western arm of Mugu Lagoon (Calleguas Creek Reach 1). Because the site is tidally influenced, an attempt is made to conduct monitoring at this site approximately one-half hour after low tide.




02D_BROOM

The monitoring site is located on an agricultural drain that discharges into Calleguas Creek Reach 2 at Broome Ranch Road.




02D_CSUCI

This site was selected as a background site for 02D_BROOM and was selected to account for nutrients, salts, or pesticides that may be contained in runoff from CSUCI grounds that ultimately makes its way to 02D_BROOM. This site is visited only if flow is present at 02D_BROOM.




04D_ETTG

This monitoring site is located on an agricultural drain just upstream from its confluence with Revolon Slough, just east of the intersection of Wood Road and Etting Road. Flow from this drain eventually discharges into Calleguas Creek Reach 4 (Revolon Slough).




04D_LAS

This monitoring site is located on an agricultural drain just upstream of its confluence with Revolon Slough just upstream of South Las Posas Road. A tile drain discharge is intermittently pumped into this ag drain upstream of the monitoring site. Flow from this drain eventually flows into Calleguas Creek Reach 4 (Revolon Slough).




05D_SANT_VCWPD

This monitoring site is located on the Santa Clara Drain east of Santa Clara Avenue at the Ventura County Watershed Protection District's Stream Gage #781. Flow from this drain eventually discharges into Calleguas Creek Reach 5 (Beardsley Channel).




05D_SANT_BKGD

This monitoring site is a background site for 05D_SANT_VCWPD and was selected to account for nutrients, salts, or pesticides that may be contained in runoff from the Saticoy Country Club and Golf Course and surrounding residential area that ultimately drains through 05D_SANT_VCWPD. This site is visited only if flow is present at 05D_SANT_VCWPD.




05D_LAVD

This monitoring site is located on the La Vista Drain just east of La Vista Avenue, north of Hwy 118. Flow from this drain eventually discharges into Calleguas Creek Reach 5 (Beardsley Channel). The Ventura County Watershed Protection District maintains a stormwater monitoring station just downstream of the VCAILG monitoring site.



05T_HONDO

This monitoring site is located on Hondo Barranca just downstream of the Hwy 118 Bridge. Hondo Barranca is a tributary to Calleguas Creek Reach 5 (Beardsley Channel).




06T_FC_BR

This monitoring site is located on Fox Barranca just upstream of the Bradley Road bridge, north of Hwy 118. Fox Barranca is a tributary to Calleguas Creek Reach 6 (Arroyo Las Posas).




06T_LONG

This monitoring site is located on Long Canyon just upstream of the Hwy 118 Bridge. Long Canyon is a tributary to Calleguas Creek Reach 6 (Arroyo Las Posas).




9BD_GERRY

This monitoring site is located on an agricultural drain adjacent to Gerry Road north of Santa Rosa Road. Flow from this drain eventually discharges into Calleguas Creek Reach 9B (Conejo Creek).




OXD_CENTR

This is the only VCAILG monitoring site in the Oxnard Coastal Watershed. The site is located on the Central Ditch, which flows under Harbor Blvd and into McGrath Lake. Water from McGrath Lake is pumped periodically into the ocean to prevent the Central Ditch from backing up and flooding Harbor Blvd.



S02T_ELLS

This monitoring site is located on Ellsworth Barranca just downstream of the Telegraph Road Bridge. Ellsworth Barranca drains the Aliso Canyon area and is a tributary to Santa Clara River Reach 2.




S02T_TODD

This monitoring site is located on Todd Barranca upstream of Hwy 126. Todd Barranca drains the Wheeler Canyon area and is a tributary to Santa Clara River Reach 2.




S03T_TIMB

This monitoring site is located on Timber Canyon Creek just upstream of Hwy 126, east of Santa Paula. Timber Creek is a tributary to Santa Clara River Reach 3.




S03T_BOULD

This monitoring site is located on Boulder Creek just upstream of Hwy 126, west of Fillmore. Boulder Creek is a tributary to Santa Clara River Reach 3.




S03D_BARDS

This monitoring site is located near the end of the agricultural drain that runs parallel to Bardsdale Avenue in Bardsdale. The drain is located on the south side of the Santa Clara River and eventually discharges into Santa Clara River Reach 3.




S04T_HOPP

This monitoring site is located on Hopper Creek just upstream of Hwy 126 and the railroad bridge. Hopper Creek is a tributary to Santa Clara River Reach 4.




S04T_TAPO

This monitoring site is located on Tapo Creek near the Ventura / Los Angeles County line, south of Hwy 126 and the Santa Clara River. Tapo Creek is a tributary to Santa Clara River Reach 4.



S04T_TAPO_BKGD

The monitoring site is a background site for S04T_TAPO that is located upstream of irrigated agricultural land that drains to S04T_TAPO. This site was selected to investigate the formation of a white floc and film on laboratory glassware and test vessels during Event 1 toxicity testing.



VRT_THACH

This monitoring site is located on Thacher Creek just upstream of Ojai Avenue in Ojai. Thacher Creek is a tributary to San Antonio Creek, which is tributary to the Ventura River.



VTR_SANTO

This monitoring site is located on San Antonio Creek just upstream of Grand Avenue in Ojai. San Antonio Creek is a tributary to the Ventura River.

